# Heavy-Duty TechTips

# TIMKEN Where You Turn

Volume 2 • Issue 1 Part 1 of a 2-Part Series

## **TAPERED ROLLER BEARING DAMAGE ANALYSIS**







The most common types of bearing damage that may result in a reduction of bearing or application life are often caused by:

- insufficient maintenance practices
- mishandling
- improper installation and adjustment practices
- inadequate lubrication

The following offers a quick reference to the common types/causes of bearing damage.

#### **FATIGUE SPALLING**



Geometric stress concentration (GSC): Spalling from misalignment, system deflections or heavy loading.



Inclusion origin: Spalling from oxides or other hard inclusions in bearing steel.




Point surface origin (PSO): Spalling from debris or raised metal exceeding the lubricant film thickness.

#### **INADEQUATE LUBRICATION\***



Roller end scoring: Metal-to-metal contact from breakdown of lubricant film.



Cone large rib face scoring: 'Welding' and heat damage from metal-to-metal contact.



Cone large rib face deformation: Metal flow from excessive heat generation.



Total bearing lock-up: Rollers skew, slide sideways and lock-up bearing.

\* Excessive preload can cause damage similar to inadequate lubrication damage.

#### HANDLING DAMAGE



Roller spaced nicking: Raised metal on races from contact with roller edges.



Rollers binding and skewing: Cage ring compressed during installation or interference during service.



Cone bore polishing: Contact wear/ creeping on the shaft, with no lubrication between the cone bore and shaft OD, caused by cone bore contraction resulting from excessive tight setting (preload).



Roller nicking/denting: Rough handling or installation damage.

#### **PEELING**



Micro-spalling due to thin lubricant film from high loads/low RPM or elevated temperatures.

#### **EXCESSIVE END PLAY**



Scalloping: Uneven localized wear resulting from excessive end play.



Cup-face denting: Indentations from hardened driver.

# OR OVERLOAD



Rapid and deep spalling caused by unusually high stresses. Full race width fatigue spalling is caused by heavy loads creating a thin lubricant film and elevated temperatures.



Cage pocket wear: Heavy contact between the rollers and cage pocket surfaces caused by bearing operating too loosely.

#### **CAGE DAMAGE**



Cage Deformation: Improperly installed or dropped bearing.

## MARNING Failure to observe the following warnings could create a risk of serious injury.

Proper maintenance and handling procedures are critical. Always follow installation instructions and maintain proper lubrication.

Never spin a bearing with compressed air. The rollers may be forcefully expelled.

TechTips is not intended to substitute for the specific recommendations of your equipment suppliers.

Every reasonable effort has been made to ensure the accuracy of the information contained in this writing, but no liability is accepted for errors, omissions or for any other reason.

### TIMKEN Where You Turn

www.timken.com

Timken® is a registered trademark of The Timken Company

© 2009 The Timken Company Printed in U.S.A. 83M 07-09-29 Order No.10308